

**National Transportation Safety Board
Washington, DC 20594**

Brief of Accident

Adopted 02/22/2000

ANC98MA008							
File No. 1877		11/08/1997		BARROW, AK		Aircraft Reg No. N750GC	
						Time (Local): 08:08 AST	
Make/Model: Cessna / 208B						Fatal	Serious
Engine Make/Model: P&W / PT6A-114						Crew	Minor/None
Aircraft Damage: Destroyed						1	0
Number of Engines: 1						Pass	0
Operating Certificate(s): Commuter Air Carrier; On-demand Air Taxi						7	0
Name of Carrier: HAGELAND AVIATION SERVICES INC							
Type of Flight Operation: Scheduled; Domestic; Passenger/Cargo							
Reg. Flight Conducted Under: Part 135: Air Taxi & Commuter							
Last Depart. Point: Same as Accident/Incident Location						Condition of Light: Night/Dark	
Destination: WAINWRIGHT , AK						Weather Info Src: Weather Observation Facility	
Airport Proximity: Off Airport/Airstrip						Basic Weather: Visual Conditions	
						Lowest Ceiling: None	
						Visibility: 7.00 SM	
						Wind Dir/Speed: 170 / 008 Kts	
						Temperature (°C): 12	
						Obstr to Vision: None	
						Precipitation: None	
Pilot-in-Command		Age: 40				Flight Time (Hours)	
Certificate(s)/Rating(s)						Total All Aircraft: 3500	
Airline Transport; Commercial; Foreign; Multi-engine Land; Single-engine Land						Last 90 Days: Unk/Nr	
Instrument Ratings						Total Make/Model: 200	
Airplane						Total Instrument Time: 100	

The pilot, who was also the station manager, arrived at the airport earlier than other company employees to prepare for a scheduled commuter flight, transporting seven passengers and cargo to another village during hours of arctic, predawn darkness. Heavy frost was described on vehicles and airplanes the morning of the accident, and the lineman who serviced the airplane described a thin glaze of ice on the upper surface of the left wing. The pilot was not observed deicing the airplane prior to flight, and was described by the other employees as in a hurry to depart on time. The pilot directed the lineman to place fuel in the left wing only, which resulted in a fuel imbalance between 450 and 991 pounds (left wing heavy). The first turn after takeoff was into the heavy left wing. The airplane was observed climbing past the end of the runway, and descending vertically into the water. No preimpact mechanical anomalies were found with the airplane or powerplant. The aileron trim indicator was found in the full right wing down position. Postaccident flight tests with left wing heavy lateral fuel imbalances, disclosed that approximately one-half of right wing down aileron control deflection was used to maintain level flight, thus leaving only one-half right wing down aileron control efficacy. Research has shown that frost on airfoils can result in reduced stall angles of attack (often below that required to activate stall warning devices), increases in stall speeds between 20% and 40%, asymmetric stalls resulting in large rolling moments, and differing stall angles of attack for wings with upward and downward deflected ailerons (as when recovering from turns).

Brief of Accident (Continued)

ANC98MA008				
File No. 1877	11/08/1997	BARROW, AK	Aircraft Reg No. N750GC	Time (Local): 08:08 AST

Occurrence #1: LOSS OF CONTROL - IN FLIGHT
Phase of Operation: TAKEOFF - INITIAL CLIMB

Findings

1. (F) FLUID,FUEL - ASYMMETRICAL
2. (F) REFUELING - IMPROPER - PILOT IN COMMAND
3. (C) AIRCRAFT WEIGHT AND BALANCE - DISREGARDED - PILOT IN COMMAND
4. (F) AIRCRAFT CONTROL - REDUCED
5. (C) STALL/SPIN - INADVERTENT - PILOT IN COMMAND
6. (C) ICE/FROST REMOVAL FROM AIRCRAFT - IMPROPER - PILOT IN COMMAND
7. (F) SELF-INDUCED PRESSURE - PILOT IN COMMAND
8. (F) INADEQUATE SURVEILLANCE OF OPERATION - COMPANY/OPERATOR MGMT

Occurrence #2: IN FLIGHT COLLISION WITH TERRAIN/WATER
Phase of Operation: DESCENT - UNCONTROLLED

Findings Legend: (C) = Cause, (F) = Factor

The National Transportation Safety Board determines the probable cause(s) of this accident as follows.

The pilot's disregard for lateral fuel loading limits, his improper removal of frost prior to takeoff, and the resulting inadvertent stall/spin. Factors involved in this accident were the improper asymmetrical fuel loading which reduced lateral aircraft control, the self-induced pressure to takeoff on time by the pilot, and inadequate surveillance of the company operations by company management.